



REPLACEMENT SHEET

ATTY DKT. NO.: MRKS/0093
U.S. SERIAL NO.: 10/613,341
FILED: JULY 3, 2003
TITLE: COUPLING TUBULARS

CONF. NO.: 5149

PAGE 2 of 4

2/4




FIG. 3




FIG. 4




FIG. 5

REPLACEMENT SHEET

ATTY DKT. NO.: MRKS/0093
U.S. SERIAL NO.: 10/613,341
FILED: JULY 3, 2003
TITLE: COUPLING TUBULARS

CONF. NO.: 5149

PAGE 3 of 4

3/4




FIG. 6




FIG. 7




FIG. 8

REPLACEMENT SHEET

ATTY DKT. NO.: MRKS/0093
U.S. SERIAL NO.: 10/613,341
FILED: JULY 3, 2003
TITLE: COUPLING TUBULARS

CONF. NO.: 5149

PAGE 4 of 4

4/4




FIG. 9